

**SECTION 3**  
**JUNK CATCHERS**

# REVERSE CIRCULATION JUNK BASKET



REVERSE CIRCULATION JUNK BASKET									
<b>Hole Size</b>		3-3/4 TO 4"	4-1/8 TO 4-1/2"	4-5/8 TO 5"	5-1/8 TO 5-1/2"	5-5/8 TO 6"	6-1/8 TO 6-1/2"	6-5/8" TO 7-3/8"	7-1/2" TO 8-1/4"
<b>Barrel OD</b>		3-5/8"	4"	4-1/2"	4-7/8"	5-1/8"	5-3/4"	6-1/4"	7"
<b>Max Fish</b>	<b>DIA.</b>	2-11/32"	2-17/32"	3-1/16"	3-9/16"	3-3/4"	4-13/32"	4-3/4"	5-3/16"
<b>Mill Teeth</b>		6	6	8	8	8	8	8	8
<b>Complete Assembly</b>	<b>Part#</b>	<b>RCB-050</b>	<b>RCB-1</b>	<b>RCB-2</b>	<b>RCB-3</b>	<b>RCB-41</b>	<b>RCB-4</b>	<b>RCB-42</b>	<b>RCB-5</b>
	Xref#	6635	7295	4448	4572	2618	2670	2677	2554
	Price	\$8,242	\$8,513	\$10,294	\$10,330	\$10,116	\$11,476	\$12,222	\$12,690

REVERSE CIRCULATION JUNK BASKET – REPLACEMENT PARTS									
<b>Top Sub</b>	<b>Part#</b>	<b>RCB-050-1</b>	<b>RCB-1-1</b>	<b>RCB-2-1</b>	<b>RCB-3-1</b>	<b>RCB-41-1</b>	<b>RCB-4-1</b>	<b>RCB-42-1</b>	<b>RCB-5-1</b>
	Xref#	6636	7296	4449	4573	2619	2671	2678	2493
	Price	\$1,420	\$1,679	\$1,679	\$1,679	\$1,614	\$2,350	\$2,428	\$2,631
<b>Barrel</b>	<b>Part#</b>	<b>RCB-050-2</b>	<b>RCB-1-2</b>	<b>RCB-2-2</b>	<b>RCB-3-2</b>	<b>RCB-41-2</b>	<b>RCB-4-2</b>	<b>RCB-42-2</b>	<b>RCB-5-2</b>
	Xref#	6637	7297	4450	4574	2620	2672	2679	2555
	Price	\$6,229	\$4,178	\$5,501	\$5,501	\$5,292	\$5,501	\$6,117	\$6,117
<b>Valve Cup</b>	<b>Part#</b>	<b>RCB-050-3</b>	<b>RCB-1-3</b>	<b>RCB-2-3</b>	<b>RCB-3-3</b>	<b>RCB-41-3</b>	<b>RCB-4-3</b>	<b>RCB-42-3</b>	<b>RCB-5-3</b>
	Xref#	6638	6638	4451	4451	2621	2621	2621	2570
	Price	\$245	\$245	\$480	\$480	\$266	\$255	\$255	\$188
<b>Steel Ball</b>	<b>Part#</b>	<b>RCB-050-4</b>	<b>RCB-1-4</b>	<b>RCB-2-4</b>	<b>RCB-3-4</b>	<b>RCB-41-4</b>	<b>RCB-4-4</b>	<b>RCB-42-4</b>	<b>RCB-5-4</b>
	Xref#	6640	6640	4453	4453	2623	2623	2623	2572
	Price	\$21	\$21	\$34	\$34	\$54	\$54	\$54	\$98
<b>Valve Seat</b>	<b>Part#</b>	<b>RCB-050-5</b>	<b>RCB-1-5</b>	<b>RCB-2-5</b>	<b>RCB-3-5</b>	<b>RCB-41-5</b>	<b>RCB-4-5</b>	<b>RCB-42-5</b>	<b>RCB-5-5</b>
	Xref#	6639	6639	4452	4452	2622	2622	2622	2571
	Price	\$83	\$83	\$83	\$83	\$129	\$129	\$129	\$166
<b>Lifting Sub</b>	<b>Part#</b>	<b>RCB-050-6</b>	<b>RCB-1-6</b>	<b>RCB-2-6</b>	<b>RCB-3-6</b>	<b>RCB-41-6</b>	<b>RCB-4-6</b>	<b>RCB-42-6</b>	<b>RCB-5-6</b>
	Xref#	4568	4568	424	424	425	425	1849	1849
	Price	\$585	\$585	\$638	\$638	\$621	\$621	\$782	\$782
<b>Junk Catcher</b>	<b>Part#</b>	<b>RCB-050-7</b>	<b>RCB-1-7</b>	<b>RCB-2-7</b>	<b>RCB-3-7</b>	<b>RCB-41-7</b>	<b>RCB-4-7</b>	<b>RCB-42-7</b>	<b>RCB-5-7</b>
	Xref#	21795W	21855W	21780W	21790W	21735W	28349W	21750W	21725W
	Price	\$1,037	\$1,037	\$1,129	\$1,073	\$1,090	\$1,420	\$1,457	\$1,605
<b>Mill Shoe Type 'A'</b>	<b>Part#</b>	<b>RCB-050-8A</b>	<b>RCB-1-8A</b>	<b>RCB-2-8A</b>	<b>RCB-3-8A</b>	<b>RCB-41-8A</b>	<b>RCB-4-8A</b>	<b>RCB-42-8A</b>	<b>RCB-5-8A</b>
	Xref#	6642A	7299A	4455A	4576A	2625A	2676A	2683A	2556A
	Price	\$1,035	\$1,035	\$1,128	\$1,072	\$1,139	\$1,445	\$1,455	\$1,604
<b>Mill Shoe Type 'B'</b>	<b>Part#</b>	<b>RCB-050-8B</b>	<b>RCB-1-8B</b>	<b>RCB-2-8B</b>	<b>RCB-3-8B</b>	<b>RCB-41-8B</b>	<b>RCB-4-8B</b>	<b>RCB-42-8B</b>	<b>RCB-5-8B</b>
	Xref#	6642B	7299B	4455B	4576B	2625B	2676B	2683B	2556B
	Price	\$1,519	\$1,631	\$1,725	\$2,069	\$2,126	\$2,432	\$2,432	\$2,546
<b>Mill Shoe Type 'C'</b>	<b>Part#</b>	<b>RCB-050-8C</b>	<b>RCB-1-8C</b>	<b>RCB-2-8C</b>	<b>RCB-3-8C</b>	<b>RCB-41-8C</b>	<b>RCB-4-8C</b>	<b>RCB-42-8C</b>	<b>RCB-5-8C</b>
	Xref#	6642C	7299C	4455C	4576C	2625C	2676C	2683C	2556C
	Price	\$1,631	\$1,725	\$1,818	\$2,154	\$2,259	\$2,536	\$2,536	\$2,722

### WHEN ORDERING, PLEASE SPECIFY:

1. Number of Assembly or Part
2. OD and Type of Shoe
3. Top Connection desired

### RECOMMENDED SPARES:

- (2) Junk Catchers
- (2) Mill Shoes
- (1) Valve Cup
- (1) Valve Seat
- (1) Steel Ball

### RECOMMENDED ACCESSORIES:

- (2) Finger Shoes
- (4) Finger Shoe Replacements
- (1) Magnet Insert

REVERSE CIRCULATION JUNK BASKET <i>(continued)</i>								
<b>Hole Size</b>		8-3/8 TO 9-1/2"	9-5/8 TO 10-5/8"	10-3/4 TO 11-5/8"	11-3/4 TO 12-1/2"	12-5/8 TO 13-5/8"	13-3/4 TO 16"	16 TO 17-1/2"
<b>Barrel OD</b>		7-7/8"	9-1/8"	10-1/8"	11"	11-7/8"	13"	15"
<b>Max Fish</b>	<b>DIA.</b>	6-1/16"	7-1/16"	7-11/16"	8-5/16"	8-11/16"	9-7/8'	11-1/8"
<b>Mill Teeth</b>		8	10	12	12	14	16	16
<b>Complete Assembly</b>	<b>Part#</b>	<b>RCB-6</b>	<b>RCB-8</b>	<b>RCB-9</b>	<b>RCB-10</b>	<b>RCB-11</b>	<b>RCB-12</b>	<b>RCB-13</b>
	Xref#	2567	2659	2684	2690	2696	2702	2708
	Price	\$12,923	\$18,926	\$20,921	\$20,697	\$26,255	\$29,128	\$42,141

REVERSE CIRCULATION JUNK BASKET – REPLACEMENT PARTS <i>(continued)</i>								
<b>Top Sub</b>	<b>Part#</b>	<b>RCB-6-1</b>	<b>RCB-8-1</b>	<b>RCB-9-1</b>	<b>RCB-10-1</b>	<b>RCB-11-1</b>	<b>RCB-12-1</b>	<b>RCB-13-1</b>
	Xref#	2568	2660	2685	2691	2697	2703	2709
	Price	\$2,917	\$4,902	\$5,092	\$5,365	\$8,113	\$9,300	\$12,154
<b>Barrel</b>	<b>Part#</b>	<b>RCB-6-2</b>	<b>RCB-8-2</b>	<b>RCB-9-2</b>	<b>RCB-10-2</b>	<b>RCB-11-2</b>	<b>RCB-12-2</b>	<b>RCB-13-2</b>
	Xref#	2569	2661	2686	2692	2698	2704	2710
	Price	\$5,883	\$8,801	\$9,322	\$8,835	\$11,189	\$11,980	\$18,563
<b>Valve Cup</b>	<b>Part#</b>	<b>RCB-6-3</b>	<b>RCB-8-3</b>	<b>RCB-9-3</b>	<b>RCB-10-3</b>	<b>RCB-11-3</b>	<b>RCB-12-3</b>	<b>RCB-13-3</b>
	Xref#	2570	2662	2662	2662	2662	2662	2662
	Price	\$196	\$273	\$273	\$273	\$273	\$273	\$273
<b>Steel Ball</b>	<b>Part#</b>	<b>RCB-6-4</b>	<b>RCB-8-4</b>	<b>RCB-9-4</b>	<b>RCB-10-4</b>	<b>RCB-11-4</b>	<b>RCB-12-4</b>	<b>RCB-13-4</b>
	Xref#	2572	2665	2665	2665	2665	2665	2665
	Price	\$98	\$265	\$265	\$265	\$265	\$265	\$265
<b>Valve Seat</b>	<b>Part#</b>	<b>RCB-6-5</b>	<b>RCB-8-5</b>	<b>RCB-9-5</b>	<b>RCB-10-5</b>	<b>RCB-11-5</b>	<b>RCB-12-5</b>	<b>RCB-13-5</b>
	Xref#	2571	2663	2663	2663	2663	2663	2663
	Price	\$166	\$347	\$347	\$347	\$347	\$347	\$347
<b>Lifting Sub</b>	<b>Part#</b>	<b>RCB-6-6</b>	<b>RCB-8-6</b>	<b>RCB-9-6</b>	<b>RCB-10-6</b>	<b>RCB-11-6</b>	<b>RCB-12-6</b>	<b>RCB-13-6</b>
	Xref#	426	427	427	427	427	427	427
	Price	\$837	\$1,035	\$1,035	\$1,035	\$1,035	\$1,035	\$1,035
<b>Junk Catcher</b>	<b>Part#</b>	<b>RCB-6-7</b>	<b>RCB-8-7</b>	<b>RCB-9-7</b>	<b>RCB-10-7</b>	<b>RCB-11-7</b>	<b>RCB-12-7</b>	<b>RCB-13-7</b>
	Xref#	18725W	14633W	18945W	21760W	21840W	21770W	21775W
	Price	\$1,665	\$1,825	\$2,613	\$2,618	\$2,873	\$3,640	\$5,473
<b>Mill Shoe</b> Type 'A'	<b>Part#</b>	<b>RCB-6-8A</b>	<b>RCB-8-8A</b>	<b>RCB-9-8A</b>	<b>RCB-10-8A</b>	<b>RCB-11-8A</b>	<b>RCB-12-8A</b>	<b>RCB-13-8A</b>
	Xref#	2574A	2668A	2689A	2695A	2701A	2707A	2713A
	Price	\$1,739	\$1,856	\$2,908	\$3,130	\$3,813	\$4,604	\$6,731
<b>Mill Shoe</b> Type 'B'	<b>Part#</b>	<b>RCB-6-8B</b>	<b>RCB-8-8B</b>	<b>RCB-9-8B</b>	<b>RCB-10-8B</b>	<b>RCB-11-8B</b>	<b>RCB-12-8B</b>	<b>RCB-13-8B</b>
	Xref#	2574B	2668B	2689B	2695B	2701B	2707B	2713B
	Price	\$2,485	\$3,226	\$3,692	\$3,869	\$4,792	\$5,687	\$7,012
<b>Mill Shoe</b> Type 'C'	<b>Part#</b>	<b>RCB-6-8C</b>	<b>RCB-8-8C</b>	<b>RCB-9-8C</b>	<b>RCB-10-8C</b>	<b>RCB-11-8C</b>	<b>RCB-12-8C</b>	<b>RCB-13-8C</b>
	Xref#	2574C	2668C	2689C	2695C	2701C	2707C	2713C
	Price	\$2,673	\$3,403	\$3,915	\$4,118	\$5,091	\$6,003	\$7,440

**NOTE:**

- Type 'A', 'B' or 'C' Shoes; Unless specified, shoes will be furnished with the same OD as minimum hole size shown.
- Shoes larger than this will be an additional 10% per 1/4" or portion thereof of standard shoe price.

# REVERSE CIRCULATION JUNK BASKET FINGER SHOES



FINGER SHOES									
Max Fish	DIA.	3-1/4"	3-3/4"	4-1/16"	4-1/2"	4-3/4"	5-17/32"	5-29/32"	6-3/4"
Complete Assembly	Part#	RCB-050-9	RCB-1-9	RCB-2-9	RCB-3-9	RCB-41-9	RCB-4-9	RCB-42-9	RCB-5-9
	Xref#	6643	7300	4456	4577	2737	2738	2739	2740
	Price	\$1,016	\$1,062	\$1,110	\$1,175	\$1,139	\$1,220	\$1,268	\$1,342
Body	Part#	RCB-050-10	RCB-1-10	RCB-2-10	RCB-3-10	RCB-41-10	RCB-4-10	RCB-42-10	RCB-5-10
	Xref#	6643-2	7300-2	4456-2	4577-2	2737-2	2738-2	2739-2	2740-2
	Price	\$553	\$571	\$613	\$645	\$623	\$672	\$700	\$762
Shoe Replacement	Part#	RCB-050-11	RCB-1-11	RCB-2-11	RCB-3-11	RCB-41-11	RCB-4-11	RCB-42-11	RCB-5-11
	Xref#	6643-1	7300-1	4456-1	4577-1	2737-1	2738-1	2739-1	2740-1
	Price	\$461	\$485	\$499	\$518	\$506	\$544	\$559	\$585

FINGER SHOES (continued)									
Max Fish	DIA.	7-23/32"	9"	9-15/16"	11"	11-7/8"	13"	15-1/4"	
Complete Assembly	Part#	RCB-6-9	RCB-8-9	RCB-9-9	RCB-10-9	RCB-11-9	RCB-12-9	RCB-13-9	
	Xref#	2741	2742	2743	2744	2745	2746	2747	
	Price	\$1,426	\$1,800	\$2,134	\$2,427	\$3,915	\$5,435	\$6,757	
Body	Part#	RCB-6-10	RCB-8-10	RCB-9-10	RCB-10-10	RCB-11-10	RCB-12-10	RCB-13-10	
	Xref#	2741-2	2742-2	2743-2	2744-2	2745-2	2746-2	2747-2	
	Price	\$792	\$969	\$1,136	\$1,262	\$2,275	\$3,432	\$4,205	
Shoe Replacement	Part#	RCB-6-11	RCB-8-11	RCB-9-11	RCB-10-11	RCB-11-11	RCB-12-11	RCB-13-11	
	Xref#	2741-1	2742-1	2743-1	2744-1	2745-1	2746-1	2747-1	
	Price	\$617	\$846	\$1,013	\$1,132	\$1,641	\$1,985	\$2,546	

**NOTE:**

- Finger Shoe Replacement is furnished with the same OD as standard shoe unless otherwise specified.
- Add 5% per 1/4" or portion thereof for shoes left oversize.

# REVERSE CIRCULATION JUNK BASKET MAGNET INSERT

MAGNET INSERT									
<b>Fits Basket</b>		C6635	C7295	C4448	C4572	C2618	C2670	C2677	C2554
<b>Number</b>		RCB-050	RCB-1	RCB-2	RCB-3	RCB-41	RCB-4	RCB-42	RCB-5
<b>Total Pull</b>	<b>LBS.</b>	25-75	75-125	75-125	125-200	125-200	250-350	350-420	450-500
<b>Complete Assembly</b>	<b>Part#</b>	<b>RCB-050-12</b>	<b>RCB-1-12</b>	<b>RCB-2-12</b>	<b>RCB-3-12</b>	<b>RCB-41-12</b>	<b>RCB-4-12</b>	<b>RCB-42-12</b>	<b>RCB-5-12</b>
	Xref#	61836	61848	61840	61850	61852	61866	61872	61947
	Price	\$2,443	\$2,807	\$2,807	\$4,037	\$3,911	\$4,866	\$5,278	\$5,697
<b>Magnetic Assembly</b>	<b>Part#</b>	<b>RCB-050-13</b>	<b>RCB-1-13</b>	<b>RCB-2-13</b>	<b>RCB-3-13</b>	<b>RCB-41-13</b>	<b>RCB-4-13</b>	<b>RCB-42-13</b>	<b>RCB-5-13</b>
	Xref#	61810	61812	61812	61814	61814	61816	61818	61820
	Price	\$2,247	\$2,639	\$2,639	\$3,822	\$3,822	\$4,634	\$5,015	\$5,416
<b>Adapter</b>	<b>Part#</b>	<b>RCB-050-14</b>	<b>RCB-1-14</b>	<b>RCB-2-14</b>	<b>RCB-3-14</b>	<b>RCB-41-14</b>	<b>RCB-4-14</b>	<b>RCB-42-14</b>	<b>RCB-5-14</b>
	Xref#	61837	61849	61841	61851	61853	61867	61873	61948
	Price	\$178	\$184	\$191	\$200	\$212	\$233	\$249	\$273

MAGNET INSERT (continued)									
<b>Fits Basket</b>		C2567	C2659	C2684	C2690	C2696	C2702	C2708	
<b>Number</b>		RCB-6	RCB-8	RCB-9	RCB-10	RCB-11	RCB-12	RCB-13	
<b>Total Pull</b>	<b>LBS.</b>	500-600	800-1000	800-1000	1000-1200	1000-1200	1200-1400	1600-1800	
<b>Complete Assembly</b>	<b>Part#</b>	<b>RCB-6-12</b>	<b>RCB-8-12</b>	<b>RCB-9-12</b>	<b>RCB-10-12</b>	<b>RCB-11-12</b>	<b>RCB-12-12</b>	<b>RCB-13-12</b>	
	Xref#	61953	61965	61967	61973	61975	61983	61985	
	Price	\$5,909	\$7,729	\$8,652	\$9,708	\$10,620	\$13,379	\$16,484	
<b>Magnetic Assembly</b>	<b>Part#</b>	<b>RCB-6-13</b>	<b>RCB-8-13</b>	<b>RCB-9-13</b>	<b>RCB-10-13</b>	<b>RCB-11-13</b>	<b>RCB-12-13</b>	<b>RCB-13-13</b>	
	Xref#	61822	61826	61826	61828	61828	61830	61832	
	Price	\$5,587	\$7,281	\$7,281	\$8,972	\$8,973	\$12,148	\$15,281	
<b>Adapter</b>	<b>Part#</b>	<b>RCB-6-14</b>	<b>RCB-8-14</b>	<b>RCB-9-14</b>	<b>RCB-10-14</b>	<b>RCB-11-14</b>	<b>RCB-12-14</b>	<b>RCB-13-14</b>	
	Xref#	61954	61966	61968	61974	61976	61982	61986	
	Price	\$309	\$429	\$621	\$743	\$860	\$1,025	\$1,212	